I'd like to share this and ask advise how to get better quality?

- Raymarine Element HV (standalone) Software rel. 3.10.10
- HV-300THP (mounted on the front of the boat

Picture is scruffy (1,2Mhz or 350khz) and hard to identify

Raymarine SideVision (Wrek 40 meter, Steel)	3rd Party SideVision (Wrek 40 meter, steel)
Using 1,2Mhz picture should be sharp and clear under 30 meters, but its not. If dept is more than 6-8 meter 350kHz is only option, but wrech is still hard to identify. 	Clear picture

3D mode cannot analyze and draw wrek, but show "points".

Size of Wreck	Real Picture
 Lenght 40 meters Dept 16m (some part only 5 meter)	

It looks Element HV cannot analyze data what it get from sensor.