Software Versions associated with Raymarine equipment

- 1. e127 MFD **V 19.03-00036**
- 2. a95 MFD **V 19.03-00036** With RMK -10 Remote MFD Keypad
- 3. (Not connected to motor Next project)
- 4. ECI-100 **V 1.20**
- 5. Fusion Radio with NMEA 2000 Remote mounted in cockpit
- 6. SeaTalkng 5 way Connector x 2
- 7. ASU 400 for Type 2 Pump **V 2.23**
- 8. iTC-5 with Speed, Water Temp (DST800), Depth (D800) and Wind Rotavecta **V 1.12**
- 9. DST 800 Speed & Water Temperature Transducer
- 10. D800 Depth Transducer
- 11. Evolution EV-1 **V 3.02**
- 12. P70R Pilot Controller V3.08
- 13. Rudder Reference Transducer
- 14. Fluxgate Compass
- 15. I70 Multi Display **V 3.16**

I have only shown the equipment and listed in the SeaTalkng network in my installation diagram.

I also have a HS5 Network Switch which has SeaTalkhs/Raynet connections to both MFD's and one other piece of equipment.